
## **Roadmap Generator**

## PUSH PERFORMANCE AND IMPROVE CONSISTENCY WITH PASON'S ROADMAP GENERATOR

Editing Roadmap 🛕 Unpublished Draft 🖸											
Cli	Click to download roadmap guidelines or sample file							کی Download CSV	🕑 Import Roadm	nap 🧳 Generate Ro	Version History   ~
	Formation	Start (ft)	End (ft)	Min WOB (klbs)	Max WOB (klbs)	Min RPM	Max RPM	Max DiffP (psi)	Max ROP (ft/hr)	Max Torque (kft lb)	Stick Slip Threshold
1	Formation 1	0	289	10	20	30	50	1490	290	30	0 1
2	Formation 2	289	860	10	30	50	75	1490	365	30	0 1
3	Formation 3	860	1031	15	30	60	80	1490	745	30	0 🗊
4	Formation 4	1031	1188	25	45	65	85	1490	425	30	0 1
5	Formation 5	1188	2100	40	50	70	90	1490	225	30	0 ti
6	Formation 6	2100	2461	25	50	40	60	1490	160	30	•
7	Formation 7	2461	2632	35	45	65	85	1490	380	30	O 🖬
8	Formation 8	2632	2881	30	65	65	85	1490	320	30	0 🖬
9	Formation 9	2881	3400	35	75	40	85	1490	875	30	0 🖬
10	Formation 10	3400	3531	60	75	60	80	1490	785	30	0 1



## BENEFITS

- Leverage offset wells to enhance drilling performance
- Improve consistency well-over-well, pad-over-pad
- Preserve bit life by identifying and mitigating troublesome formations

pason

## FEATURES

- Use machine learning with offset wells to generate roadmaps
- Upload formations or use auto-detection
- Automate with DAS and Toolface Control